

**Updated FY 2010 REP/VMP Budgets**

**Table 1. REP O&M Activities**

<u>Activities</u>	<u>FY 2010 Budgeted Expenses</u>
Inspection and Maintenance	\$20,000
O&M related to Capital Expenditures	\$75,000
<b>Total</b>	<b>\$95,000</b>

**Table 2. VMP O&M Activities<sup>1</sup>**

<u>Activities</u>	<u>FY 2010 Budgeted Expenses</u>
Spot Tree Trimming	\$59,000
Trouble and Restoration Maintenance	\$59,000
Planned Cycle Trimming	\$693,000
Cycle Trimming Police Detail Expenses	\$65,000
Hazard Tree Removal	\$304,500
Interim Trimming	\$82,000
Tree Planting	\$500
Other Police Detail Expenses	\$14,000
<b>Total</b>	<b>\$1,277,000</b>

**Table 2a. Enhanced Hazard Tree Removal**

<u>Activities</u>	<u>FY 2010 Budgeted Expenses</u>
Enhanced Hazard Tree Removal	\$100,000
<b>Total</b>	<b>\$100,000</b>

<sup>1</sup> Budget items included in Table 2 are based on work price estimates.

**Table 3. REP Capital Investments**

<u>Projects</u>	<u>Goal</u>	<u>FY 2010 Budgeted Investments</u>
<b>Feeder Hardening</b>	25 miles	\$320,000
<b>Reclosers</b>	6 reclosers	\$240,000
<b>Asset Replacement</b>		
- Cutouts: Installing new cutouts on side taps per engineering study and replacing potted porcelain cutouts	220 cutouts	\$60,000
<b>Total</b>		<b>\$620,000</b>

**Fiscal Year 2010 Feeder Hardening & Asset Replacement Details**

<b>Program/Feeder</b>	<b>Description</b>
Cutout Replacement	Install new side tap fuses to minimize the number of customers affected by individual faults and replace potted porcelain cutouts. The Company expects a total of 220 cutouts to be installed/replaced in FY10 as part of the base capital budget.
Vilas Bridge 12L1	Recloser installation
Mt. Support 16L1	Recloser installation
Spicket River 13L2	Recloser installation
Salem 9L3	Recloser installation
Salem 9L3	Recloser installation
Salem 9L3	Recloser installation
Barron Ave. 10L4	14 miles of feeder hardening
Salem Depot 9L3	11 miles of feeder hardening in FY10 (25 total feeder miles on 9L3, of which 14 miles were done in FY 09 project)