

October 8, 2020

## **City of Somersworth Double Pole Priorities\***

- Green St., in front #27 (FP 20/12) 224801 – POWER AND CATV STILL ATTACHED TO OLD POLE.
- Green St., in front #9 (FP 20/8) 224801– POWER AND CATV STILL ATTACHED TO OLD POLE.
- Indigo Hill Road at RR track crossing – EVERSOURCE ONLY
- Indigo Hill Road at Pole # 1/146-old pole; new pole #7/146
- Green Street at old Pole #20/23; new pole # 206 20/23
- Green Street at Pole #20/22; new pole # 20/22
- Green Street a new Pole #20/23 ½; old Pole # 23 ½
- Green Street at Pleasant St .Pole # 2/4, pole is leaning toward sidewalk by granite wall
- Green Street at new Pole #2/20; old Pole #2/20
- Green Street at new Pole # 2/21; old Pole # 26 2/21
- Green Street at old Pole # 203/28X;
- Franklin St at Silver Pole # 18/5.
- Franklin Street. Pole # 18/6
- Franklin Street –old pole, 33/15, new pole 18/13
- Franklin Street-new pole # 18/14,
- Indigo Hill Road at Green St, 202/21, new pole 202/1, old pole is 202/1
- Indigo Hill Road by William Street, pole # 7/142; pole in sidewalk.
- 361 High Street, Pole # 3/68 –suggest move meter to outside of pole, to allow safe passage of sidewalk tractor.
- 67A Maple Street, Pole # 95/12 1. Pole is leaning and looks unsafe.

These are priority poles that are located on or impact sidewalks that the City Public Works crews clear as priority walking routes; the double poles create safety hazards for City operators when clearing the sidewalks and limits accessible for all pedestrians; places these areas in non –compliance with ADA regulations.