



Exhibit 01 Photos of the Pennichuck Watershed




















Watershed protection land with trails to the banks of the ponds.



Path is clear to see and leads to the pond (2005)



Path is a worn highway near Manchester Street to reservoir




People fishing on the bank of reservoir near a rope swing



Canoes stashed in the woods for future use



Fences down from falling trees and not well maintained






Reservoir with pretty slimy vegetation on the surface



Everett Turnpike culvert letting
Boire Brook
water into
Reservoir





Beer bottle, computer monitor, and other trash dumped by water leading into Reservoir



Watershed with town marked

