



32 Artisan Court #2
Gilford, NH 03249

Invoice

DW 19-131
Exhibit 33

Date	Invoice #
9/22/2020	8933

Bill To

PC Construction
Attn: Shawn Flynn
[Transmitted by Email to:
sflinn@pcconstruction.com]

**PLEASE MAKE CHECK PAYABLE TO:
NEW ENGLAND SERVICE COMPANY**

**MAIL CHECK TO:
37 NORTHWEST DRIVE
PLAINVILLE, CT 06062**

		P.O. No.	Service Date	Terms	Due Date
		Verbal - Shawn Fly...	September 14, 2020	Net 30	10/22/2020
Qty	Description	Unit Cost		Amount	
9.25	Labor charge for time spent on valve locating at the Omni Mount Washington Hotel addition in Bretton Woods, NH 03575 On September 14, 2020 the NESC technician arrived on site around 11:30am. None of the valves were marked out. He had to wait for the area to be excavated in order to attempt to locate them. The two (2) new valves were unable to be found. - 4.5 hours On September 22, 2020 the NESC technician opened the specified valves on the property. Both the 4" and 6" valves were opened slowly to allow the system to pressurize. - 4.75 hours	90.00		832.50	

Interested in paying this invoice online? Please visit our website (www.newenglandservicecompany.com) and select "Make a Payment" at the top right side of the homepage.

If you have any questions concerning this invoice, please call
Ryan Caouette at (860) 747-1665.

Late payment charge applied after past due: Greater of \$2.00 or 1.5% of delinquent balance per month. All collections & legal costs will be added to your balance due if your account is sent to collections.

Subtotal	\$832.50
Sales Tax (6.35%)	\$0.00
Payments/Credits	\$0.00
Balance Due	\$832.50

www.NewEnglandServiceCompany.com
Specializing in Water System Operations and Maintenance
(860) 747-1665 | customerservice@newenglandservicecompany.com

New England Service Company
NEW HAMPSHIRE JOB ORDER

Date of Order: 8-19-19 Time: 9:30 - 4:00 PM AM/PM System: Rosebrook
Caller's Name: MT Washington Hotel Telephone #: _____
Owner's Name: _____ Telephone #: _____
Address: Carbarns Building
Bill To: MT Washington
Bill To Address: _____
Account #: _____ Appt. Date & Time: _____ MIU #: _____
Meter Size: _____ Meter #: _____ Install Date: _____
Nature of Request/Call: Mark out water lines and Hydrant.

— They are tearing down the building and wanted the water turned off. No valve visible, Hydrant #60 has a gate on the side wall, confirmed gate operates the hydrant only by blasting hydrant.

Description of Work Completed: - Hooked up locator to main line inside building and traced out to near gate valve of Hydrant. MT.W had backhoe excavator dig up location to expose gate valve box, box full of dirt so proceeded to excavate out old gate box, exposed gate and shut off using gate key, confirmed water was off in building.

MATERIAL/EQUIPMENT/SUBCONTRACTORS USED (ATTACH PACKING, SALES SLIPS, ETC.)

went to pump station to find replacement Gate box for

Qty	Description	Vendor	PO#	Unit Cost	Amount
	<u>Gate Valve. They are going to tear down building and will have to move the main in order to put up new building in location.</u>				
	<u>Pulled meter S/N: 69734416 Gal: 4836533 Sensus 2"</u>				
<u>8-19-19</u>		<u>FJP</u>	<u>1557</u>		

Technician: Phil S Hours Worked: 6.5 Date: 8-19-19